



**F<sup>2</sup>MC-16 Family**  
**16-bit Microcontroller**  
**SOFTUNE Assembler Additional Manual**

## 1. List of Added Options

The added start-up options are listed in *Table 1*.

### ■ List of Added Options

Table 1 List of Added Options

Format	Function outline	Initial value
<b>Target-dependent option</b>		
-div905	Does not replace <i>DIV/DIVW</i> instruction with alternative instruction	Does not replace
-xdiv905	Replaces <i>DIV/DIVW</i> instruction with alternative instruction	
-div_check	Does not issue warning message warning to <i>DIV/DIVW</i> instruction	Issues warning message
-xdiv_check	Issues warning message to <i>DIV/DIVW</i> instruction	

## 2. Details of Added Options

---

The added start-up options are explained.

---

### ■ Added Options

There are four added options as follows:

- `-div905` ······ Does not replace *DIV/DIVW* instruction with alternative instruction
- `-xdiv905` ······ Replaces *DIV/DIVW* instruction with alternative instruction
- `-div_check` ···· Does not issue warning message warning to *DIV/DIVW* instruction
- `-xdiv_check` ··· Issues warning message to *DIV/DIVW* instruction

## 2.1 -div905 and -xdiv905

---

These options relate to nonconformity in the "DIV A,Ri" and "DIVW A,RWi" instructions of the MB90500 series.

The -div905 option does not replace the *DIV/DIVW* instruction with an alternative instruction.

The -xdiv905 option replaces the *DIV/DIVW* instruction with an alternative instruction.

These options are valid only for the F<sup>2</sup>MC-16 family (MB90500 series).

---

### ■ -div905

#### [Format]

```
-div905
```

#### [Explanation]

This option does not replace the *DIV/DIVW* instruction with an alternative instruction.

#### [Example]

```
fasm907s -cpu mb90500 test -div905
```

#### <Caution>

- 
- The -div905 option is valid only for the F<sup>2</sup>MC-16 family (MB90500 series).
- 

### ■ -xdiv905

#### [Format]

```
-xdiv905
```

#### [Explanation]

This option replaces the *DIV/DIVW* instruction with an alternative instruction.

#### [Example]

```
fasm907s -cpu mb90500 test -div905 -xdiv905
```

#### <Caution>

- 
- The -xdiv905 option is valid only for the F<sup>2</sup>MC-16 family (MB90500 series).
-

■ Nonconformity in "DIV A,Ri" and "DIVW A,RWi" Instructions of MB90500 Series

If the value of a bank register (DTB, ADB, USB, SSB) is 00<sub>H</sub>, the remainder resulting from the execution of the "DIV A,Ri" and "DIVW A,RWi" instructions is stored in a general-purpose register used as the instruction operand.

However, if the bank register value is not 00<sub>H</sub>, the remainder is stored in the bank memory specified by the bank register at the same address as that of the general-purpose register used as the operand.

For the bank register corresponding to each instruction, see *Table 1-2-2*.

Table 1-2-2 Bank Register Corresponding to Each Instruction

Instruction	Bank register
<i>DIV A,R0</i> <i>DIV A,R1</i> <i>DIV A,R4</i> <i>DIV A,R5</i> <i>DIVW A,RW0</i> <i>DIVW A,RW1</i> <i>DIVW A,RW4</i> <i>DIVW A,RW5</i>	DTB
<i>DIV A,R2</i> <i>DIV A,R6</i> <i>DIVW A,RW2</i> <i>DIVW A,RW6</i>	ADB
<i>DIV A,R3</i> <i>DIV A,R7</i> <i>DIVW A,RW3</i> <i>DIVW A,RW7</i>	USB *1 SSB

\*1: USB is used if the S-bit of the CCR register is set.  
SSB is used otherwise.

**Example:** Remainder resulting from operation of DIV A,R0 when DTB = 053<sub>H</sub> / RP = 003<sub>H</sub>

The address of R0 is 00180<sub>H</sub> + 003<sub>H</sub> \* 010<sub>H</sub> + 08<sub>H</sub> = 0001B8<sub>H</sub>.

Since the bank register specified by "DIV A,R0" is DTB, the memory bank takes on 053<sub>H</sub>.

Thus, the remainder is stored at 05301B8<sub>H</sub>.

The V30L04 or later version of *εasm907s* has a function for replacing the above instructions with trouble-free equivalent instruction strings, thereby circumventing problems.

There is no problem if the bank register value is 00<sub>H</sub>.

The F<sup>2</sup>MC-16F families and the MB90400 series of the F<sup>2</sup>MC-16LX families do not have such nonconformity.

## 2.2 -div\_check and -xdiv\_check

---

These options relate to nonconformity in the "DIV A,Ri" and "DIVW A,RWi" instructions of the MB90500 series.

The `-div_check` option issues a warning message to the *DIV/DIVW* instruction.

The `-xdiv_check` option does not issue a warning message to the *DIV/DIVW* instruction.

These options are valid only for the F<sup>2</sup>MC-16 family (MB90500 series).

---

### ■ -div\_check

#### [Format]

```
-div_check
```

#### [Explanation]

This option issues a warning message to the *DIV/DIVW* instruction.

#### [Example]

```
fasm907s -cpu mb90500 test -div_check
```

#### <Caution>

- 
- The `-div_check` option is valid only for the F<sup>2</sup>MC-16 family (MB90500 series).
- 

### ■ -xdiv\_check

#### [Format]

```
-xdiv_check
```

#### [Explanation]

This option does not issue a warning message to the *DIV/DIVW* instruction.

#### [Example]

```
fasm907s -cpu mb90500 test -div_check -xdiv_check
```

#### <Caution>

- 
- The `-xdiv_check` option is valid only for the F<sup>2</sup>MC-16 family (MB90500 series).
-

### 3. Added Error Message

---

The added error message is shown below.

---

#### ■ Added Error Message

W1805A	Invalid instructions (DIV, DIVW) are detected
--------	---

[Program processing]

Continues processing