

# Motorola Semiconductor Engineering Bulletin

---

## EB260

## Why an MC68300 or MC68HC16 Microcontroller May Fail to Release Reset

By Charles Melear  
Austin, Texas

### Introduction

---

The most common reasons that a device from either of the MC68300 or MC68HC16 Families fails to come out of reset are:

- The pullup resistor on the RESET pin is too large. This pullup resistor should be no larger than 1 k.
- A capacitor is connected from the RESET pin to ground.

In no case should a capacitor be connected to the RESET pin.

**NOTE:** *Poor oscillator design and implementation can also cause the device to fail to release reset.*

### General Information

---

This is what happens to the RESET pin during a power-on condition:

- When power is applied to the device, the RESET pin is driven low.
- The voltage-controlled oscillator (VCO) achieves phase-lock, and sets the SLOCK bit in the synthesizer control register (SYNCR).



- The RESET line is driven low for 512 clock periods. At the end of the 512-clocks, the line is released and allowed to be pulled up by an external device. After 10 or 14 cycles have elapsed, the RESET line is again sampled. If the RESET pin is at a logic 0, the internal circuitry pulls it low for an additional 512 cycles, releases it for 10 or 14 cycles, and then samples it again. If the RESET pin is read as a logic 1 at the end of the 10- or 14-cycle period, the internal RESET signal is released on the intermodule bus and the device begins operation by fetching the initial stack pointer and program counter values. Once again, if the RESET signal fails to reach a logic 1 level in the prescribed time, check the value of the pullup resistor and be certain that no capacitors are connected to the RESET pin.

### Considerations When Not Using the VCO

---

When the voltage-controlled oscillator (VCO) is not being used, it is important to hold the RESET line in its asserted (low) condition until both the power supply and the clock are stable.

As soon as the RESET line is released, the device will start counting the 512-clock period. If the clock is unstable or has entered a meta-stable mode, the clock frequency could be considerably outside the operating range of the device. If the clock is still unstable at the end of the 512-clock period, problems are sure to arise. Usually, the device will not operate if this is the case.

### Low-Voltage Inhibit for Reset Release


---

Putting a low-voltage inhibit (LVI) device on the RESET pin will prevent the release of RESET before the power supply has reached its final value. More importantly, the LVI will prevent the device from entering an unknown state, if the power supply dips below specified minimum operating voltage and then rises back to proper operating level. If this

situation (commonly called a brown-out) occurs, the device may no longer function correctly and may not respond to a RESET signal.

To ensure that a brown-out condition will not cause the device to malfunction, an LVI chip can place the device in RESET while the device is still in a known operating condition. Then, if a brown-out does occur, the device will be held in a known condition while the power is below the operating range of the part.

When power is restored, RESET will be released by the LVI chip and the device will operate normally.

Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters which may be provided in Motorola data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part. Motorola and  are registered trademarks of Motorola, Inc. Motorola, Inc. is an Equal Opportunity/Affirmative Action Employer.

#### How to reach us:

**USA/EUROPE/Locations Not Listed:** Motorola Literature Distribution, P.O. Box 5405, Denver, Colorado 80217, 1-800-441-2447 or 1-303-675-2140. Customer Focus Center, 1-800-521-6274

**JAPAN:** Motorola Japan Ltd.: SPD, Strategic Planning Office, 141, 4-32-1 Nishi-Gotanda, Shinagawa-ku, Tokyo, Japan, 03-5487-8488

**ASIA/PACIFIC:** Motorola Semiconductors H.K. Ltd., Silicon Harbour Centre, 2 Dai King Street, Tai Po Industrial Estate, Tai Po, New Territories, Hong Kong, 852-26629298

**Mfax™, Motorola Fax Back System:** RMFAX0@email.sps.mot.com; <http://sps.motorola.com/mfax/>;  
TOUCHTONE, 1-602-244-6609; US and Canada ONLY, 1-800-774-1848

**HOME PAGE:** <http://motorola.com/sps/>

Mfax is a trademark of Motorola, Inc.



**MOTOROLA**

© Motorola, Inc., 1999

EB260/D