

## *Mask Set Errata 5*

# 68HC908AZ60 8-Bit Microcontroller Unit

---

---

## INTRODUCTION

---

---

This mask set errata provides information pertaining to the index mode instructions applicable to these 68HC908AZ60 MCU mask set devices:

- 2J74Y, 4J74Y
- 5J61D
- 8H62A

---

---

## MCU DEVICE MASK SET IDENTIFICATION

---

---

The mask set is identified by a 5-character code consisting of a version number, a letter, two numerical digits, and a letter, for example 2J74Y. Slight variations to the mask set identification code may result in an altered version number, for example 4J74Y.

---

---

## MCU DEVICE DATE CODES

---

---

Device markings indicate the week of manufacture and the mask set used. The date is coded as four numerical digits where the first two digits indicate the year and the last two digits indicate the work week. For instance, the date code "9115" indicates the 15th week of the year 1991.

---

---

## MCU DEVICE PART NUMBER PREFIXES

---

---

Some MCU samples and devices are marked with an SC or XC prefix. An SC prefix denotes special/custom device. An XC prefix denotes that the device is tested but is not fully characterized or qualified over the full range of normal manufacturing process variations. After full characterization and qualification, devices will be marked with the MC prefix.

*When contacting a Motorola representative for assistance, please have the MCU device mask set and date code information available.*

Specifications and information herein are subject to change without notice.



## INDEX MODE INSTRUCTIONS


---

When unmapped locations are accessed with data from an unmapped address using indexed mode instructions, an illegal address reset occurs. For example, the location \$FE15 is not mapped for the 68HC908AZ60. When the location is read using the following instructions, an illegal address reset occurs when LDA ,X is executed.

```
LDHX $FE15
LDA ,X
```

The indexed mode instructions that cause this problem are the same instructions that originally came from the M68HC05 such as STA and ORA. However, the newer M68HC08 instructions such as MOV do not cause the illegal address reset.

To avoid this illegal address reset, do not access data from an unmapped location using an instruction with an address determined by the contents of the H:X registers. However, an opcode fetch from an unmapped address generates an illegal reset.

Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters which may be provided in Motorola data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part. Motorola and  are registered trademarks of Motorola, Inc. Motorola, Inc. is an Equal Opportunity/Affirmative Action Employer.

Additional mask set erratas can be found on the World Wide Web at <http://mcu.motsps.com/documentation>



**MOTOROLA**

68HC908AZ60MSE5