

MB89160 Series

DS07-12405-2E

© Fujitsu Mikroelektronik GmbH

13.03.2000

Vers. 1.0

This document describes known bugs regarding the MB89160 Series:

In the MB89160 Data Sheet "DS07-12405-2E", there is a typo at p. 35.
The device mentioned "MB89PV165" actually refers to "MB89P165".