

## MB89530 Series

© Fujitsu Mikroelektronik GmbH

13.03.2000

Vers. 1.0

**This document describes known bugs regarding the MB89530 Series**

The "Package and corresponding products" table (page 4) states that:

- '538 type devices are available in LQFP (M03) packages
- 'P538 are not available in LQFP (M03) packages
- '538 are not available in QFP (M06) packages

This, however, is not consistent with "Ordering Information" (page 46) since this table gives ordering numbers for 'P538 in M03 package and '538 in M06 package.

Also, there are no ordering numbers for '538 in M03 packages.

Correction:

DIP-64P-M01: MB89537/538/537H/538H/P538

FTP-64P-M03: MB89537/538/537H/538H

FTP-64P-M06: MB89537/538/537H/538H/P538

FTP-64P-M09: MB89537/538/537H/538H/P538

Last Modification: 23. December 1999

---