



Corrections of Hardware Manual

MB89160 -

HM89160_add_V100

© Fujitsu Microelectronics Europe GmbH

Addendum, MB89160 Hardware Manual (CM25-10103-4E)

This is the Addendum for the Hardware Manual CM25-10103-4E of the MB89160 microcontroller series. It describes all known discrepancies of the MB89160 microcontroller series Hardware Manual.

Ref. Number (Text Link)	Date dd.mm.yy	Version No.	Chapter/Page	Description/Correction
HWM89160001		V1.00		No known errors

HWM89160001

No known errors

Addendum, MB891600 Datasheet (DS07-12405-2E)

This is the Addendum for the Datasheet (DS07-12405-2E) of the MB89160 microcontroller series. It describes all known discrepancies of the MB89160 microcontroller series datasheet.

Ref. Number (Text Link)	Date dd.mm.yy	Chapter/Page	Description/Correction
DS89160001	26.05.00	Electrical characteristics, page 35	Typo, the device mentioned "MB89PV165" actually refers to "MB89P165"

DS89160001

Electrical Characteristics, page 35:

There is a typo at p. 35.

The device mentioned "MB89PV165" actually refers to "MB89P165"