



## Corrections of Hardware Manual

MB89190 -

HM89190\_add\_V100

© Fujitsu Microelectronics Europe GmbH

### Addendum, MB89190 Hardware Manual (Revision 2)

This is the Addendum for the Hardware Manual (Revision 2) of the MB89190 microcontroller series. It describes all known discrepancies of the MB89190 microcontroller series Hardware Manual.

Ref. Number (Text Link)	Date dd.mm.yy	Version No.	Chapter/Page	Description/Correction
<a href="#">HWM89190001</a>	26.05.00	V1.00	Chapter 13.3.2	RCR2 Register: do not use Read-Modify- Write instructions

HWM89190001

Chapter 13: Remote Control

Do not use read-Modify-Write instructions for register RCR2.

Otherwise sometimes first RCO output pulse isn't put out.