



Corrections of Hardware Manual

MB89940 -

HM89940_add_V100

© Fujitsu Microelectronics Europe GmbH

Addendum, MB89940 Hardware Manual (hm89940-v-0-91a)

This is the Addendum for the Hardware Manual hm89940-v-0-91a of the MB89940 microcontroller series. It describes all known discrepancies of the MB89940 microcontroller series Hardware Manual.

Ref. Number (Text Link)	Date dd.mm.yy	Version No.	Chapter/Page	Description/Correction
HWM89940001	07.07.00	V1.00	17.1/72	DDR 2 access correction

HWM89940001

Register Map at adress 000DH Port 2 Data Direction Register **only Write Access** possible