


NO. 544 S.A.M.I. - PROJECTOR
(COMPLETE ASSEMBLY 71-001)



NOTE
CAUTION: DO NOT PLACE TOO MUCH TENSION ON FILM LOOP WHEN TIGHTENING IDLER BRACKETS (71-015). THE ADJUSTABLE IDLER BRKT. (71-015) HAS BEEN REPLACED BY AN IDLER STUD (71-702) ON SOME MODELS.

NOT SHOWN:
PROJ. BASE BOARD 544-508
PROJ. DUST COVER 71-134
FILM LOOP ASS'Y. 71-013