

There have been reports from WKUSB users that WinXP will remap the WKUSB USB port to a different address. I have not been able to determine what causes this to happen, it seems to be computer dependent. In any case here is the procedure I use to set the WK USB driver to a specific com port. –Steve K1EL

First of all click on Start then Right click on *My Computer*:



Click on *Properties*:



Click on *Hardware*:



Click on *Device Manager*.




Then Double Click on *Ports (COM & LPT)* to expand the port list:




Double click on *USB Serial Port (COMx)* (actual com port will be specific to your PC)




Click on *Port Settings*:




Click on *Advanced*:



Finally you will see the port selection control:



By clicking on the down arrow to the right of the COM Port Number List Box you will get a list of available com ports. Click on the one you want and you are finished.



In the event you installed a new USB com port or reassigned a different port the com port you last used may not be available. In that case you will need to map WKUSB to a new com port.